

ML261SM Surface Mounted Single Toilet Roll Holder with Hood

Material Specifications

- #304 Stainless Steel Body and Hood
- Chrome Plated Die Cast Zamak Brackets
- Chrome Plated ABS Roller

Mounting

- Surface Mount Visible Fix

Dimensions

- 167mmH x 167mmW x 78mmD

Finish





- **ML261SM_S**: Satin Stainless Steel With Hood
- **ML261SM_B**: Polished Stainless Steel With Hood



Installation Guidelines

- *May be subject to Australian Building Code Regulations for height and location fixing and may be subject to placement as per architectural drawings. In all cases, this is the responsibility of the installer.*
1. Locate fixing position in the wall and mark using the fixing holes on the rear of the toilet roll holder.
 2. Using screws and wall plugs provided, pre-screw the holes.
 3. On the perimeter of the toilet roll holder, place a suitable amount of an adhesive or high strength bonding agent.
 4. Loosely secure unit to wall surface using fixings.
 5. Level the unit, then push firmly so that it sits flush with the wall.
 6. Firmly screw the toilet roll holder into place and leave the adhesive to set for 24 hours before using.

ML261_SM



Features

- Holds one standard toilet roll.



This product is AS1428.1 compliant (accessible compliant) when installed in accordance with the guidelines.

The technical recommendations contained in this document are necessarily of a general nature and should not be relied on for specific applications without first securing competent advice. Whilst Metlam Australia Pty Ltd has taken all reasonable steps to ensure the information contained herein is accurate and current, it does not warrant the accuracy or completeness of the information and does not accept liability for errors or omissions. Any Commercial product should only be installed by a competent tradesperson and serviced/maintained by knowledgeable janitorial staff or competent people. Metlam Australia accepts no responsibility for any damage to product, walls or fixtures due to incorrect installation or maintenance of any of their products.